

Customer Service Report

Schedule Now For Service

September 2025

Call 802-223-3452

Work Order # 0292077465

Customer Since: 2018

<p style="text-align: center;">System Owner</p> <p>Sallie Astheimer 2019 Fuller Hill Road Warren, VT 05674 610-442-5736</p>	<p style="text-align: center;">System Location</p> <p>Primary Home 2019 Fuller Hill Road Warren, VT 05674 Sallie Astheimer : 610-442-5736</p>
--	--

<p>Service Date: Sep 09/03/2024 12:00 AM</p> <p>Service Type: Septic Tank</p> <p>Approx. Gals.: 1000</p> <p>Depth Below: 0</p> <p>Cust Home: YES</p> <p>Township:</p> <p>County: Washington</p>	<p>Frequency:</p> <p>Previous Service: 06/30/2021</p> <p>System Treatment:</p> <p>Custom Clean:</p> <p>Filter</p> <p>Inspection/T5:</p> <p>Build Up:</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">Tank Size</th> <th colspan="8">Household Occupancy</th> </tr> <tr> <th>1</th><th>2</th><th>3</th><th>4</th><th>5</th><th>6</th><th>7</th><th>8</th> </tr> </thead> <tbody> <tr> <td>1000</td><td>22</td><td>20</td><td>18</td><td>16</td><td>14</td><td>12</td><td>12</td><td>12</td> </tr> <tr> <td>1250</td><td>22</td><td>20</td><td>18</td><td>18</td><td>16</td><td>14</td><td>12</td><td>12</td> </tr> <tr> <td>1500</td><td>24</td><td>22</td><td>20</td><td>20</td><td>18</td><td>16</td><td>14</td><td>14</td> </tr> <tr> <td>2000</td><td>26</td><td>24</td><td>22</td><td>22</td><td>20</td><td>18</td><td>16</td><td>16</td> </tr> </tbody> </table>	Tank Size	Household Occupancy								1	2	3	4	5	6	7	8	1000	22	20	18	16	14	12	12	12	1250	22	20	18	18	16	14	12	12	1500	24	22	20	20	18	16	14	14	2000	26	24	22	22	20	18	16	16
Tank Size	Household Occupancy																																																						
	1	2	3	4	5	6	7	8																																															
1000	22	20	18	16	14	12	12	12																																															
1250	22	20	18	18	16	14	12	12																																															
1500	24	22	20	20	18	16	14	14																																															
2000	26	24	22	22	20	18	16	16																																															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Description</th><th>Qty</th><th>Unit Price</th><th>Ext. Price</th></tr> </thead> <tbody> <tr> <td>OS-R-Pumping 1000</td><td>1.00</td><td>\$398.3684</td><td>\$398.37</td></tr> <tr> <td>Coupon-Customer Appreciation</td><td>1.00</td><td>-\$25.0000</td><td>-\$25.00</td></tr> <tr> <td>Coupon-BOOKNOWCSR75</td><td>1.00</td><td>-\$75.0000</td><td>-\$75.00</td></tr> <tr> <td colspan="3" style="text-align: right;">Subtotal:</td><td>\$298.37</td></tr> <tr> <td colspan="3" style="text-align: right;">Tax:</td><td>\$0.00</td></tr> <tr> <td colspan="3" style="text-align: right;">Total:</td><td>\$298.37</td></tr> </tbody> </table>		Description	Qty	Unit Price	Ext. Price	OS-R-Pumping 1000	1.00	\$398.3684	\$398.37	Coupon-Customer Appreciation	1.00	-\$25.0000	-\$25.00	Coupon-BOOKNOWCSR75	1.00	-\$75.0000	-\$75.00	Subtotal:			\$298.37	Tax:			\$0.00	Total:			\$298.37	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Score From Table</td><td style="text-align: right;">20</td></tr> <tr> <td>Garbage Disposal (-6)?</td><td style="text-align: right;">0</td></tr> <tr> <td>System Age > 10 Years (-5)?</td><td style="text-align: right;">-5</td></tr> <tr> <td>Seasonal Occupancy (+8)?</td><td style="text-align: right;">0</td></tr> <tr> <td>System Treatment Used (+5)?</td><td style="text-align: right;">0</td></tr> <tr> <td>Total Adjustments?</td><td style="text-align: right;">-5</td></tr> <tr> <td>Net Score</td><td style="text-align: right;">15</td></tr> </table>	Score From Table	20	Garbage Disposal (-6)?	0	System Age > 10 Years (-5)?	-5	Seasonal Occupancy (+8)?	0	System Treatment Used (+5)?	0	Total Adjustments?	-5	Net Score	15											
Description	Qty	Unit Price	Ext. Price																																																				
OS-R-Pumping 1000	1.00	\$398.3684	\$398.37																																																				
Coupon-Customer Appreciation	1.00	-\$25.0000	-\$25.00																																																				
Coupon-BOOKNOWCSR75	1.00	-\$75.0000	-\$75.00																																																				
Subtotal:			\$298.37																																																				
Tax:			\$0.00																																																				
Total:			\$298.37																																																				
Score From Table	20																																																						
Garbage Disposal (-6)?	0																																																						
System Age > 10 Years (-5)?	-5																																																						
Seasonal Occupancy (+8)?	0																																																						
System Treatment Used (+5)?	0																																																						
Total Adjustments?	-5																																																						
Net Score	15																																																						
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Score</th><th>Service Every</th></tr> </thead> <tbody> <tr> <td>< 5</td><td>6 Months</td></tr> <tr> <td>6 - 15</td><td>12 Months</td></tr> <tr> <td>16 - 23</td><td>18 Months</td></tr> <tr> <td>24+</td><td>24 Months</td></tr> </tbody> </table>	Score	Service Every	< 5	6 Months	6 - 15	12 Months	16 - 23	18 Months	24+	24 Months																																											
Score	Service Every																																																						
< 5	6 Months																																																						
6 - 15	12 Months																																																						
16 - 23	18 Months																																																						
24+	24 Months																																																						

<p><input type="checkbox"/> System Normal Keep your system healthy by following these 3 steps:</p> <ul style="list-style-type: none"> • Regular Service • Use WRE Septic System Treatment • Use a Filter <p><input type="checkbox"/> Excessive Solids Use WRE Septic System Treatment</p> <p><input type="checkbox"/> Heavy Sludge Use WRE Septic System Treatment</p> <p><input type="checkbox"/> Tee Missing/Broken Repair/Replace Tee</p> <p><input type="checkbox"/> High Liquid Level Possible system failure. Call for evaluation or customer cleaning.</p> <p><input type="checkbox"/> Distribution Box Issue See notes below for details.</p>	<p>Schedule Now for Service September 2025 Call 802-223-3452</p> <p>Payment Detail: Discover xxxxxxxxxxx9137 11/2025 Due on Receipt</p> <p>X _____ Customer Signature</p>
--	--

Technician: Micah Collins **Arrived at:** 10:51 AM **Left at:** 11:37 AM

Tech Notes:
System Operating Fine. Low water level. Light top solids. Light bottom sludge. Both baffles are intact. Main line Clear. No filter is present on the tank; current tank can be outfitted with a filter. Cover(s) secured. Pumped about a thousand gallons from the septic tank. Recommended No Recommendation. Tech Recommendation: No Recommendation - None



THIS IS NOT AN INVOICE.





